



PECO ENERGY

Walter G. MacFarland, IV, P.E.
Vice President
Limerick Generating Station

PECO Energy Company
PO Box 2300
Salatoga, PA 19464-0920
610 718 3000
Fax 610 718 3008
Pager 1 800 352 4732 #8320

T.S. 4.0.5
10 CFR 50.55a (g)
May 19, 1995

Docket No. 50-353
License No. NPF-85

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

SUBJECT: Limerick Generating Station, Unit 2
Summary Reports for Inservice Inspections
and ASME Section XI Repairs and Replacements

Enclosed are the reports:

- 1) Limerick Generating Station, Unit 2 Summary report for the March 17, 1993 to February 19, 1995 Period Inservice Inspection - Report No. 3.
- 2) Limerick Generating Station, Unit 2 Summary of ASME Section XI Repairs and Replacements completed from March 17, 1993 to February 19, 1995 - Report No. 3

These reports are being submitted pursuant to Technical Specification Surveillance Requirements 4.0.5 and 10CFR50.55a(g).

If you have any questions, or require additional information, please do not hesitate to contact us.

Very truly yours,

Enclosures

9505250102 950519
PDR ADDCK 05000353
PDR

cc: T. T. Martin, Administrator, Region I, USNRC
N. S. Perry, USNRC Senior Resident Inspector, LGS

AOA7
11