




ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649



TELEPHONE
AREA CODE 716 546-2700
Ginna Station
February 18, 1975



Mr. James P. O'Reilly
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Abnormal Occurrence 75-05: Failure of the 1C Safety Injection Pump
to start manually from Bus 16
Ginna Station Docket #50-244

Dear Mr. O'Reilly:

This is to confirm my phone call to Mr. John Streeter this morning to report
Abnormal Occurrence #75-05 at Ginna Station.

While conducting Periodic Test PT-2.1 this morning, the 1C Safety Injection
Pump failed to start from Bus 16 when the control switch was manually activated
in the Control Room. The control switch was immediately actuated again, and this
time the pump started. The 1A and the 1B Safety Injection Pumps were then tested
satisfactorily.

The PORC met and recommended further investigation of the breaker on Bus 16, and
a thorough check of the Bus 14 - Bus 16 interlock scheme at the breaker on Bus 14.
The 1C Safety Injection Pump is to be started once a week from Bus 16 until the
PORC changes the frequency of testing.

Very truly yours,

Charles E. Platt
Charles E. Platt
Superintendent

CEP:fah

cc: Mr. Edson G. Case, NRC
Mr. G. J. Swarthout, RG&E
Mr. L. D. White, Jr., RG&E

8304050667 750226
PDR ADOCK 05000244
S PDR

2053