



**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704


AREA CODE 409 838-6631

April 16, 1984

RBG- 17604

File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV, Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1  
Docket No. 50-458  
Final Report/DR-143

Gulf States Utilities Company has completed its investigation of DR-143 concerning instrument tubing supports in the Auxiliary Building and has determined this condition is not reportable under 10CFR50.55(e).

Sincerely,

*L. Q. England for*

J. E. Booker  
Manager-Engineering,  
Nuclear Fuels & Licensing  
River Bend Nuclear Group

PJD  
JEB/PJD/kt

cc: Director of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

NRC Resident Inspector-Site

8404260245 840416  
PDR ADOCK 05000453  
S PDR

IE-27 1/0