

LICENSEE EVENT REPORT

CONTROL BLOCK:

1					6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME							LICENSE NUMBER							LICENSE TYPE					EVENT TYPE					
0	1	N	Y	N	M	P	1	5		-					-		4	1	1	1	1	0	1	
7	8	9					14	15								25	26					30	31	32

01		CONT		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE									
7	8	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
		M	I	L	L	0	5	0	-	0	2	2	0	0	6	2	5	7	6	0	7	0	1	7	6

EVENT DESCRIPTION

02	Operator noted smoke from relay 4-112 B/40, Reactor Recirculation Pump - Lo Lo Level	80
03	Trip (#12HFA51A49F). Relay assumed the tripped condition thus no hazard was presented	80
04	to plant or general public.	80
05	RO 76-23	80
06		80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION			
0	7	I	B	E	I	N	S	T	R	U	N	G	0	8	0	-
7	8	9	10	11	12					17	43	44				48

CASE DESCRIPTION

08	Coil apparently short causing smoking and blown fuse. Relay replaced with similar	80
7 8 9		
03	device.	80
7 8 9		
10		80
7 8 9		

11	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
7 8	9 C	10 0 11 8 12 1	13	44 a 45	46
FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE		
12	9 2	10 2 11 N/A	44	45	
7 8					

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	0	0	0	N/A

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	N/A

OPPOSITE CONSEQUENCES probable

15 NONE

7 8 9

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
15	2	0	NONE

PUBLICITY

17 | NONE

ADDITIONAL FACTORS

13 1
7 8 9
PDR ADDUCK 0500V EE
S PDR

8304060499 760701
PDR ADCK 05000220
S PDR

IE FILE COPY

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD, WEST
SYRACUSE, N. Y. 13202

July 6, 1976




Mr. James P. O'Reilly
Directorate of Regulatory Operations
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pa. 29406

RE: Docket No. 50-220

In accordance with Nine Mile Point Nuclear Station Unit #1
Environmental Technical Specification 5.6.3.1, we hereby submit Licensee
Event Reports 76-23, 76-24, and 76-25.

This report was completed within the intent of the Licensee
Event Report Instruction Booklet 00E-SS-001, dated October 1974, re-
vised December 24, 1974. Due to the minimal significance category of
the report, no supplemental report is included.

Very truly yours,



R. R. Schneider
Vice President -
Electric Operations

TJD/aih
Enc.

COPY SENT REGION I

7569