

LER 76-25/3L
LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: 01 N Y R E G 1 14
 LICENSE NUMBER: 0 0 - 0 0 0 0 0 0 - 0 0 25
 LICENSE TYPE: 4 1 1 1 1 30
 EVENT TYPE: 0 3 31 32
 CATEGORY: 01 CONT 57 58
 REPORT TYPE: L 59
 REPORT SOURCE: L 60
 DOCKET NUMBER: 0 5 0 - 0 2 4 4 68
 EVENT DATE: 1 0 1 0 7 6 74
 REPORT DATE: 1 1 0 9 7 6 80

EVENT DESCRIPTION

02 During operation of RHR system an operator noted small puddle on floor and discovered
 03 leak at weldolet to nipple weld on 3/4" vent on RHR return line. This is similar to
 04 Reportable Occurrence 74-5. Replaced nipple and rewelded using approved procedures.
 05 (Reportable Occurrence 76-25, 30-day).
 06

SYSTEM CODE: 07 C P 10
 CAUSE CODE: B 11
 COMPONENT CODE: P I P E X X 17
 PRIME COMPONENT SUPPLIER: N 43
 COMPONENT MANUFACTURER: K 0 5 5 47
 VIOLATION: N 48

CAUSE DESCRIPTION

08 Stresses were induced due to improper fitup of nipple to socket during construction.
 09 Nipple appeared bottomed in socket. New nipple properly installed.
 10

FACILITY STATUS: 11 G 9
 % POWER: 0 0 0 10 12 13
 OTHER STATUS: NA 44
 METHOD OF DISCOVERY: a 45
 DISCOVERY DESCRIPTION: By operator 46
 FORM OF ACTIVITY RELEASED: 12 Z 9
 CONTENT OF RELEASE: Z 10
 AMOUNT OF ACTIVITY: NA 44
 LOCATION OF RELEASE: NA 45

PERSONNEL EXPOSURES

13 NUMBER: 0 0 0 11
 TYPE: Z 12
 DESCRIPTION: NA 13

PERSONNEL INJURIES

14 NUMBER: 0 0 0 11
 DESCRIPTION: NA 12

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

16 TYPE: Z 10
 DESCRIPTION: NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

19

8304070116 761109
 PDR ADOCK 05000244
 S PDR

NAME: Jack Noon

PHONE: 716/546-2700, ext. 291-215

REE

TE FILE COPY



NEW
YORK
STATE

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

November 9, 1976




Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence 76-25 (30-day report), Leak at Residual
Heat Removal System return pipe vent
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.9.2b, the attached report of Reportable Occurrence 76-25, 30-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,


L. D. White, Jr.

Attachment

cc: Dr. Ernst Volgenau (30)
Mr. William G. McDonald (3)

11531