

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

April 16, 1984

TELEPHONE
(704) 373-4531

✓ Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: McGuire Nuclear Station, Units 1 and 2
Docket Nos. 50-369 and 50-370
LER 369/84-09

Gentlemen:

On March 14, 1984 the NRC was notified (via ENS Report) of a possible lack of containment integrity involving the reactor vessel level indication system on Unit 2, which was later expanded to include Unit 1. Pursuant to 10 CFR 50.73(a)(1) and (d), Licensee Event Report LER 369/84-09 was to have been submitted by April 13, 1984. At this time, all of the required information is not yet available, the complete report will be submitted by April 24, 1984.

Very truly yours,

H. B. Tucker
Hal B. Tucker

PBN:dyh

cc: Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. T. Orders
NRC Resident Inspector
McGuire Nuclear Station

IE22
1/0

8404270203 840416
PDR ADDCK 05000369
S PDR