



telegram

=DEB412 SSE468

DE JLA194 ZO NL PD=TDJL MORRIS ILL 17=

BOYCE GRIER DIRECTOR DIVN COMPLIANCE REGION 3=

US ATOMIC ENERGY 799 ROOSEVELT RD GLEN ELLYN ILL=

SUBJECT DPR19 DRESDEN NUCLEAR POWER STATION UNIT TWO:=

THIS WILL CONFIRM CONVERSATION 1600 HOURS THIS DATE
WITH H DANCE REGARDING FAILURE OF THE HPCI TO START AS
REQUIRED DURING ROUTINE SURVEILLANCE TESTING AT 2200 ON
11/16/71. THE PROBLEM WAS FOUND TO BE A LOOSE LIMIT
SWITCH ON THE CONTROL VALVE. THE SWITCH ADJUSTING SCREW
WAS TIGHTENED AND A DOUBLE LOCK NUT WAS ADDED TO PROTECT
AGAINST FURTHER LOOSENING. DURING THE PERIOD PRIOR TO
SATISFACTORY DEMONSTRATION OF HPCI OPERABILITY AT 0015

WU 1201 (R 5-68)

THIS DATE THE HPCI WAS DECLARED INOPERABLE AND
SURVEILLANCE INITIATED AS REQUIRED BY SECTION 3.5C OF
THE TECHNICAL SPECIFICATIONS. THIS ITEM IS REPORTED
UNDER SECTION 6.6.A.3 OF THE TECHNICAL SPECIFICATIONS=

H K HOYT DRESDEN NUCLEAR POWER STATION COMMONWEALTH
EDISON RR #1 MORRIS ILLINOIS.==

B304080022 711119
PDR ADOCK 05000237
Q PDR

TELEPHONE NO. 858-2660
TELEPHONED TO Sgt
TIME DELIVERED 1248
BY 45 TO BE Mid

DPR19 1600 H DANCE 2200 11/16/71 0015 3.5.C 6.6.A.3 #1.1.1.==

1 5011

NOV 18 1971

WU 1201 (R 5-69)

Copy sent PDR

MEMO ROUTE SLIP

Form AEC-93 (Rev. May 14, 1947) AECM 0240

See me about this.
Note and return.

For concu
For signature

For action.
For information.

TO (Name and unit) J. G. Keppler CO:HQ	INITIALS DATE	REMARKS TWX INCIDENT REPORT - DRESDEN 2 (50-237)
TO (Name and unit)	INITIALS DATE	REMARKS
TO (Name and unit)	INITIALS DATE	REMARKS
FROM (Name and unit) G. Fiorelli CO:III <i>G. Fiorelli</i>	REMARKS	In accordance with PI 1000, attached is the original TWX report dated November 18, 1971, reporting inoperable HPCI.
PHONE NO. 858-2660	DATE 11-19-71	

USE OTHER SIDE FOR ADDITIONAL REMARKS