

October 2, 1974




Mr. Angelo Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Giambusso:

**TURKEY POINT UNIT NO. 3
DOCKET NO. 50-250
INSPECTION OF SAFETY RELATED
HYDRAULIC PIPE RESTRAINTS**

Inspection of the safety related pipe restraints that are accessible during power operation was completed on September 20, 1974, in accordance with the continuing requirements of the Atomic Energy Commission Directorate of Licensing letter of November 8, 1973. All of the restraints were found to be in satisfactory condition. The inspection included a total of 20 restraints and all are of the Bergen-Paterson design.

Very truly yours,


Robert E. Uhrig
Vice President

REU/HNP/cpc

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire