



August 30, 1974


Mr. Angelo Giambusso  
Deputy Director for Reactor Projects  
Directorate of Licensing  
Office of Regulation  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Dear Mr. Giambusso:

TURKEY POINT UNIT NO. 3  
DOCKET NO. 50-250  
INSPECTION OF SAFETY RELATED HYDRAULIC  
PIPE RESTRAINTS

Inspection of the safety related pipe restraints that are accessible during power operation was completed on August 19, 1974, in accordance with the continuing requirements of the Atomic Energy Commission Directorate of Licensing letter of November 8, 1973. All of the restraints were found to be in satisfactory condition. The inspection included a total of 20 restraints and all are of the Bergen-Paterson design.

Very truly yours,

  
R. E. Uhrig  
Vice President

REU/DWR/cpc

cc: Mr. Norman C. Moseley  
Jack R. Newman, Esquire

8304110139 741024  
PDR ADOCK 05000251  
Q PDR

50-250  
ingury  
9258  
HEL COPY SENT REGION