



June 25, 1974

Mr. Angelo Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545




Dear Mr. Giambusso:

TURKEY POINT UNIT NO. 4
DOCKET NUMBER 50-251
REINSPECTION OF SAFETY RELATED
HYDRAULIC PIPE RESTRAINTS ACCESSIBLE
DURING POWER OPERATION

Reinspection of the accessible safety related piping restraints in accordance with the continuing requirements of the Directorate of Licensing letter of November 8, 1973, was completed on June 13, 1974. There were 15 restraints inspected and all are of the Bergen-Paterson design. The inspection showed that all of these restraints were in satisfactory condition.

Very truly yours,



R. E. Uhrig
Vice President

REU/HNP/kmw

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire

Handwritten:
50251
R.E.
24

8304110170 741024
PDR ADDCK 05000251
Q PDR

COPY SENT REGION 

6016