

April 23, 1974



Mr. Angelo Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Giambusso:

**TURKEY POINT UNIT NO. 3
DOCKET NUMBER 50-250
REINSPECTION OF SAFETY RELATED
HYDRAULIC PIPE RESTRAINTS ACCESSIBLE
DURING POWER OPERATION**

Reinspection of the accessible safety related piping restraints in accordance with the continuing requirements of the Directorate of Licensing letter of November 8, 1973, has been completed. There were 20 restraints inspected and all are of the Bergen-Paterson design. The inspection showed that all of these restraints were in satisfactory condition.

Very truly yours,

R. E. Uhrig
Director of Nuclear Affairs

HNP/kmw

cc: Mr. Norman C. Moseley
Mr. Jack R. Newman



Handwritten:
hurd
R. E. B.
22-4
50250

3913