



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

TELEPHONE
AREA CODE 716 546 2700

Gianna Station
July 13, 1977

KVS

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence # 77-10
Redundant Service Water Dis-
charge Line Support Design Error

Dear Mr. O'Reilly:

This is to confirm my phone call to Mr. Donald Haverkamp on July 14, 1977 to report supplemental information regarding Reportable Occurrence # 77-10 at Gianna Station.

Following discovery of this Reportable Occurrence, Gilbert Associates was directed to review the redundant house service discharge line completely. As a result of this review four additional supports (SW-69, SW-73, SW-78, SW-83) could produce, under design basis earthquake conditions, stresses in excess of applicable allowable values as was previously identified for SW-70. We are proceeding to rectify the condition.

Bruce A. Snow
Bruce A. Snow
Assistant Superintendent

RAS:KBB

cc: Mr. G. J. Swarthout, RGE Corp.
Mr. L. D. White, Jr., RGE Corp.

8304120727 770720
PDR ADDCK 05000244
S PDR