

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14647

LEONARD WHITE, JR.
VICE PRESIDENT

September 17, 1976



Director of Nuclear Reactor Regulation
ATTN: Mr. Karl Goller
Assistant Director for Operating Reactors
Division of Reactor Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Subject: Inspection of Hydraulic Shock Absorbers (Snubbers)
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. Goller:

In accordance with Mr. Skovholt's letter of October 1, 1973, concerning periodic inspection of hydraulic shock absorbers (snubbers), an inspection of all snubbers both inside and outside of containment was completed on September 7, 1976.

All snubbers were considered operable at this inspection. No fluid additions were necessary. The non-safety related Bergen-Paterson unit outside of containment, reported in our letter dated August 3, 1976 to have exhibited leakage at the shaft seal, had been replaced on August 4, 1976.

Very truly yours,


L. D. White, Jr.

3630

8304120744 760917
PDR ADOCK 05000244
Q PDR

COPY SENT REGION 