



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

October 10, 1975

Director of Nuclear Reactor Regulation
ATTN: Mr. Karl Goller
Assistant Director for Operating Reactors
Division of Reactor Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555



Subject: Inspection of Hydraulic Shock Absorbers (Snubbers)
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244


IE FILE COPY

Dear Mr. Goller:

In accordance with Mr. Skovholt's letter of October 1, 1973, concerning periodic inspection of hydraulic shock absorbers (snubbers), an inspection of all snubbers outside of containment was completed on October 3, 1975.

All snubbers were considered operable at this inspection. Fluid was added to one safety related unit. Leakage was indicated from this Bergen-Paterson unit at the accumulator piston seal. Surveillance will be increased on this unit until plant conditions will facilitate its repair.

Very truly yours,


L. D. White, Jr.

8304210245 751223
PDR ADDCK 05000244
G PDR

COPY SENT REGION I 11978