



NEW  
YORK  
STATE

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 546-2700

July 3, 1975

Mr. Karl Goller  
Assistant Director for Operating Reactors  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Subject: Inspection of Hydraulic Shock Absorbers (Snubbers)  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. Goller:

In accordance with Mr. Skovholt's letter of October 1, 1973 concerning periodic inspection of hydraulic shock absorbers (snubbers), an inspection of all snubbers, both inside and outside of containment, was completed on June 20, 1975.

All snubbers were considered operable at this inspection. No units on safety related systems exhibited leakage or required fluid addition. One Grinnell unit on a non-safety related system exhibited fluid reservoir gasket leakage, and required fluid added. Repair of this unit will follow receipt of necessary spare parts, which are on order.


Very truly yours,

L. D. White, Jr.

8304210255 751223  
PDR ADOCK 05000244  
PDR  
Q

COPY SENT REGION I

7201



50-244  
inquiry