

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

January 14, 1975



Mr. Karl Goller
Assistant Director for Operating Reactors
Directorate of Licensing
U. S. Atomic Energy Commission
Washington, D. C. 20545


Subject: Inspection of Hydraulic Shock Absorbers (Snubbers)
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. Goller:

The hydraulic snubber units located outside the containment were inspected on January 3, 1975. All units were determined to be operable.

Hydraulic fluid was added to the reservoir of one of these Bergen-Paterson units. This unit presently has ethylene propylene seals. The source of leakage could not be immediately determined. Surveillance frequency on this unit will be increased until corrective maintenance is performed.

Very truly yours,


L. D. White, Jr.

8304210292 751223
PDR ADOCK 05000244
Q PDR

628