

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14619

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

December 13, 1974

Mr. Karl Goller
Assistant Director for Operating Reactors
Directorate of Licensing
U. S. Atomic Energy Commission
Washington, D. C. 20545



Subject: Inspection of Hydraulic Shock Absorbers (Snubbers)
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. Goller:

The hydraulic snubber units located outside the containment were inspected on December 6, 1974, and the units located inside the containment were inspected on December 10, 1974, when a containment entry was made. All units were determined to be operable.

A small quantity of hydraulic fluid was added to the reservoirs of four Bergen-Paterson units outside the containment. These units presently have ethylene propylene seals.

Two more Grinnell units were added to the east condenser steam dump line during the inspection period.

Very truly yours,

L. D. White, Jr.
L. D. White, Jr.

*50-244
incident*

8304210297 751223
PDR ADOCK 05000244
Q PDR

12711

COPY SENT REGION I