

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546 2700

October 28, 1974



Mr. Karl Goller
Assistant Director for Operating Reactors
Directorate of Licensing
U. S. Atomic Energy Commission
Washington, D.C. 20545


Subject: Inspection of Hydraulic Shock Absorbers (Snubbers)
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. Goller:

In accordance with Mr. Skovholt's letter of October 1, 1973 concerning periodic inspection of hydraulic shock absorbers (snubbers), an inspection of all snubbers, both inside and outside of containment, was conducted during the period of October 10, 1974 through October 14, 1974.

All snubbers were considered operable at this inspection. A small quantity of hydraulic fluid was added to three snubbers which were located outside of the containment. This was the first addition of fluid to any of these units in approximately four months. There was no definite indications of leakage in the area.

Very truly yours,


L. D. White, Jr.

8304210306 751223
PDR ADOCK 05000244
Q PDR

50-244
incident
11124
I
COPY SENT REGION