



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

GRANGER E. GREEN
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

September 23, 1974



Mr. Karl Goller
Assistant Director for Operating Reactors
Directorate of Licensing
U. S. Atomic Energy Commission
Washington, D.C. 20545

Subject: Inspection of Hydraulic Shock Absorbers (snubbers)
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. Goller:

In accordance with Mr. Skovholt's letter of October 1, 1973 concerning periodic inspection of hydraulic shock absorbers (snubbers), inspections of all snubbers were conducted by station maintenance personnel.

On September 13, 1974, all hydraulic snubbers located outside of the containment were inspected. All oil reservoirs were at normal levels.

On September 18, 1974, all hydraulic snubber units inside the containment vessel were inspected and all oil reservoirs were at proper levels.

There was no evidence found of any fluid leakage during either of the inspections.

Very truly yours,

Granger E. Green

8304210311 751223
PDR ADDCK 05000244
G PDR

50-244
Inquiry
10121

COPY SENT REGION

J