



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

October 21, 1975

Director of Nuclear Reactor Regulation
ATTN: Mr. Karl Goller
Assistant Director for Operating Reactors
Division of Reactor Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Subject: Inspection of Hydraulic Shock Absorbers (Snubbers)
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. Goller:

In accordance with Mr. Skovholt's letter of October 1, 1973, concerning periodic inspection of hydraulic shock absorbers (snubbers), an inspection of all snubbers, both inside and outside of containment, was completed on October 14, 1975.

All snubbers were considered operable at this inspection. The Bergen-Paterson unit outside of containment, reported in our letter dated October 10, 1975 to have leakage indicated, was removed for repair of the accumulator. Fluid addition was made to one other Bergen-Paterson unit outside of containment although there was no leakage exhibited.

Very truly yours,


L. D. White, Jr.

8304210394 751021
PDR ADDCK 05000244
PDR
Q

COPY SENT REGION 