

50-237

NNNN"!!""NR



R B

MSG NR 617

M

USAEC HQS GTWN

TLXA404 KAO23

K VEB449 JQ PDBITDVE CHICAGO ILL 19 1240P CDT

DONALD SKOVHOLT ASST DIR FOR OPERATING REACTORS DIRECTORATE
OF LICENSING DLR DONT FONE

US ATOMIC ENERGY COMM WASHDC 20545

THIS IS TO INFORM YOU THAT THE REPAIR OF THE DRESDEN UNIT 2
MAIN STEAMLINES BY PINNING OF THE DOWN STREAM FLOW RESTRICTOR
CONES HAVE BEEN COMPLETED. THE MODIFICATION HAS BEEN REVIEWED
AND APPROVED BY THE COMMONWEALTH EDISON NUCLEAR REVIEW BOARD
AND DRESDEN UNIT 2 IS EXPECTED TO BE RETURNED TO SERVICE LATE
ON SEPTEMBER 19 1972R

L D BUTTERFIELD COMMONWEALTH EDISON CO

2 2 19 1972.(807)

113A EDT

USAEC HQS GTWN

50-237
inquiry

5166

8304210544 720219
PDR ADDCK 05000237
P PDR