



Carolina Power & Light Company

Brunswick Steam Electric Plant

P. O. Box 10429

Southport, NC 28461-0429

April 10, 1984

FILE: B09-13510C

SERIAL: BSEP/84-0989

Mr. James P. O'Reilly, Administrator
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

DOCKET NO. 50-324

LICENSE NO. DPR-62

SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8 AND
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (2-SR-84-5)

Dear Mr. O'Reilly:

During an ongoing Unit 2 refueling and maintenance outage on March 16, 1984, a fire barrier LCO was initiated to permit the replacement of an equipment hatch, located in the Diesel Generator Building, being done in accordance with a plant modification. Due to the extended time period required for performing the involved work, the specified seven-day time frame of the subject LCO has been exceeded. Until the completion of the ongoing work and return of the subject hatch to service, appropriate stationed fire watches will be maintained.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/jah/LETC1

cc: Mr. R. C. DeYoung
NRC Document Control Desk

8405070144 840410
PDR ADOCK 05000324
S PDR

110
IE22