

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

April 16, 1984

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

INSPECTION AND ENFORCEMENT BULLETIN 83-06 - NONCONFORMING MATERIALS
SUPPLIED BY THE TUBE-LINE CORPORATION FACILITIES AT LONG ISLAND CITY,
NEW YORK; HOUSTON, TEXAS; AND CAROL STREAM, ILLINOIS

Please refer to L. M. Mills' letters to you dated November 22, 1983 and
February 2, 1984, which contained our responses to Bulletin 83-06. After
reviewing those two submittals, it appeared our response for Browns Ferry
could be considered inconclusive. We would like to point out that the
analysis for Browns Ferry revealed that no Tube-Line supplied materials
have been furnished for use in safety-related systems.

If you have any questions, please get in touch with R. H. Shell at FTS
858-2688.

To the best of my knowledge I declare the statements contained herein are
complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

DS Kammer

D. S. Kammer
Nuclear Engineer

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

259
260
396
8405070157 840416
PDR ADOCK 05000259
Q PDR