



Carolina Power & Light Company

84 APR 30 3:47  
P. O. Box 165, New Hill, North Carolina 27562  
April 16, 1984

FILE: SH N-2/18  
Item 166

MQAH 84-167

Mr. James P. O'Reilly  
United States Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Northwest  
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT, UNIT NO. 1  
DOCKET NO. 50-400

MINIMUM WALL FOR 32" CARBON STEEL ELBOWS ON MAIN STEAMLINES

Dear Mr. O'Reilly:

This is to confirm the April 13, 1984 telephone conversation between Mr. K. V. Hate' (CP&L) and Mr. A. Hardin (NRC). Mr. Hardin was informed that the March 14, 1984 potentially reportable item, pertaining to several 32" carbon steel mainsteam elbows having wall thickness readings that were below the minimum values specified by the design documents, has been evaluated and considered not to be reportable per the provisions of 10CFR50.55(e) and 10CFR, Part 21.

Thank you for your consideration in this matter.

Yours very truly,

NJC/mt

cc: Mr. R. C. DeYoung  
Mr. G. Maxwell  
Mr. R. L. Prevatte

*N J Chiangi*  
N. J. Chiangi - Manager  
Quality Assurance/Quality Control  
Harris Plant  
*by KGH*

8405070472 840424  
PDR ADOCK 05000400  
S PDR

11A  
IE27