

TENNESSEE VALLEY AUTHORITY  
CHATTANOOGA, TENNESSEE  
37401



April 26, 1974

Mr. John F. O'Leary, Director  
Directorate of Licensing  
Office of Regulation  
U.S. Atomic Energy Commission  
Washington, DC 20545

Dear Mr. O'Leary:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 -  
DOCKET NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - ABNORMAL  
OCCURRENCE REPORT BFAO-7417W (AMENDMENT)

The enclosed report is to supplement BFAO-7417W, in which a  
commitment was made to provide additional information when the  
cause of failure was determined. The failure of suppression  
chamber to drywell vacuum breaker valve FCV 64-28M to fully  
close as indicated by a check light occurred on Browns Ferry  
unit 1 on March 15, 1974.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*E. F. Thomas*  
E. F. Thomas  
Director of Power Production



Enclosure  
CC (Enclosure):

Mr. Norman C. Moseley, Director  
Region II Regulatory Operations Office, USAEC  
230 Peachtree Street, NW., Suite 818  
Atlanta, Georgia 30303

*Printed 5-759*

3776

8305060119 740426  
PDR ADCK 05000259  
S PDR

COPY SENT REGION 11