



**Boston Edison**

Pilgrim Nuclear Power Station  
Rocky Hill Road  
Plymouth, Massachusetts 02360

**E. T. Boulette, PhD**  
Senior Vice President - Nuclear

March 21, 1995  
BECO Ltr. #95- 037

U.S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555

Docket No. 50-293  
License No. DPR-35

PNPS response to the NRC staff request for additional information  
concerning the proposed repair of the Pilgrim Core Shroud

Enclosed is Boston Edison Company's response to your request for additional information. The responses were prepared by GE in conjunction with and under the direction of Pilgrim. Supplemental information concerning the questions raised by the staff is provided in Enclosure 3. If further information is required please contact Mr. David Heard at 508-830-8800 or Mr. Robert Haladyna at 508-830-7904.

*E. T. Boulette, PhD*  
E. T. Boulette, PhD

ETB/nas/Rap95/Coruadd

- Enclosure 1: GE Responses to NRC Questions for Pilgrim Shroud Repair, March 1995, DRF B11-00617-19, Rev. 2  
Enclosure 2: Shroud Mechanical Repair Program, Pilgrim Nuclear Power Plant, Supplement A to Shroud Repair Hardware Stress Analysis, March, 1995 GENE-771-79-1194, Supplement A to Revision 2  
Enclosure 3: Additional Information concerning Question 9, Question 21, and Question 24

cc: Mr. R. Eaton, Project Manager  
Division of Reactor Projects - I/II  
Mail Stop: 14D1  
U. S. Nuclear Regulatory Commission  
1 White Flint North  
11555 Rockville Pike  
Rockville, MD 20852

U.S. Nuclear Regulatory Commission  
Region I  
475 Allendale Road  
King of Prussia, PA 19406

Senior Resident Inspector  
Pilgrim Nuclear Power Station

9506060209 950321  
PDR ADDCK 05000293  
P PDR

*Corrected  
& returned to LCO  
by PRR - 6/15/95  
APOL  
1/1*