

Western union

Telegram

858-2010

449P EST MAY 1 72 DEB994

SSQ023 DE CCA232 (SF 122CC106232)PD WU TSDEPT MOLI 0421P EDT05/01/72  
TELEPHONE NO. 858-3260

ZCZC 001 DG PD TDMS CORDOVA ILL 1 300P CST VE TELEPHONED TO  
U S ATOMIC ENERGY COMM ATTN DUANE BOYD TIME DELIVERED 1259P  
REGION 3 COMPLIANCE 799 ROOSEVELT RD GLEN ELLYN ILL 60137  
BT

REFERENCE QUAD CITIES NUCLEAR POWER STATION - DPR-30 APPENDIX A 5 59  
SECTION 6.6.A.2 AND 6.6B.1 - WHILE CHECKING JET PUMP FLOWS ON  
THE QUAD CITIES POWER STATIONS UNIT 2 REACTOR ON APRIL 28, 1972  
AT 530PM JET PUMPS NUMBER 19 AND 20 INDICATED LESS THAN 50 PERCENT  
OF THE OTHER JET PUMP FLOWS. JET PUMP NUMBER 20 WAS REMOVED AND  
THE RISER OBSTRUCTION WAS DISCOVERED ON APRIL 29 1972 AT 5PM.  
THE OBSTRUCTION WAS A HEILARC WELDING OUTFIT. THIS IS REPORTED  
AS INCIDENT NUMBER 2-72-4 AND REGION 3 COMPLIANCE WAS NOTIFIED  
IMMEDIATELY BY PHONE

SF-1201 (R5-69)

COMMONWEALTH EDISON CO QUAD CITY NUCLEAR POWER STATION  
B B STEPHENSON  
NNNN(0424P EDT)

8305180753 720508  
PDR ADOCK 05000265  
S PDR

MAY 5 1972

SF-1201 (R5-69)

Copy sent PDR

2 0699