



Telegram

VEA275(1645)(1-034617A312)PD 11/08/74 1645

1974 NOV -8 PH 3: 51

ICS IPMVEID MVN

04085 TDVE MORRIS IL 98 11-08 1256P CST

PMS JAMES G KEPPLER REGIONAL DIRECTOR DIRECTORATE OF REGULATORY
OPERATIONS REGION 3 WUX US ATOMIC ENERGY COMM 799 ROOSEVELT RD
GLEN ELLYN IL 60137

SUBJECT: DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2.

THIS WILL CONFIRM A CONVERSATION WITH PHIL JOHNSON OF YOUR
OFFICE AT 1030 HOURS THIS DATE CONCERNING FAILURE OF FEEDWATER
CHECK VALVES IN 2B FEEDWATER LINE TO PASS LOCAL LEAK RATE TESTS
DURING REFUEL OUTAGE SURVALIENCE. OVERHAUL WILL COMMENCE UPON
COMPLETION OF REPAIRS TO 2A CHECK VALVES.

IN ADDITION EXCESS LEAKAGE IS ALSO REPORTED THROUGH THE SHAFT
PACKING OF DRY-WELL TO TOROS VACUUM BREAKERS 1601-32D AND 1601-33D.
OVERHAUL OF VACUUM BREAKERS IS IN PROGRESS AT THIS TIME

B B STEPHENSON, SUPERINTENDENT DRESDEN NUCLEAR POWER STATION

8305190081 741108
PDR ADOCK 05000237
PDR

50-237
incident



western union

Telegram

NOV 8 1974

COMMONWEALTH EDISON COMPANY RRI MORRIS ILLINOIS 60450

NNNN

TELEPHONE NBR. 312-858-2660
TELEPHONED TO P9 BY SC90
DATE DLD 11/8 TIME 447P
ATTEMPTS TO DELIVER.
mail

NOV 12 1974

SF-1201 (R5-69)

60450