



Commonwealth Edison
Quad-Cities Generating Station
Post Office Box 218
Cordova, Illinois 61242
Telephone 309/654-2241

NJK-74-255

Telecopy: Region III, Attention: Mr. C. Feierabend

August 31, 1974

J. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
U. S. Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station, Unit 2
Docket No. 50-265, DPR-30
Appendix A, Sections 1.0.A.2, 3.7.A.3.a, 6.6.B.1.a,

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.

While performing quarterly surveillance tests on the Unit 2 Torus-Reactor Building vacuum breaker valves, AO-2-1601-20A would not operate from the control room. The Unit was in the process of starting up following a scram, and control rod withdrawal was terminated. Maintenance found a defective pilot solenoid valve, and it was replaced. The 2-1601-20A valve was then operated successfully from the control room.

This occurrence was discussed by telephone with Mr. Feierabend of your office on August 31, 1974. Further information will be provided by Abnormal Occurrence Report AO 50-265/74-21 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis
N. J. Kalivianakis
Station Superintendent

NJK/LFG/lp

cc: Directorate of Licensing
J. S. Abel

8305190166 740910
PDR ADOCK 05000265
S PDR

SEP 3 1974