

MGMCGBC CGO  
2-028252 E277 10/04/74  
ICS IPMBNGZ CSP  
8159422920 MGM TDBN MORRIS IL 110 10-04 0307P EDT  
ZIP 60137



Mailgram



JAMES G KEPPLER REGIONAL DIRECTOR DIRECTORATE OF REGULATORY OPERATION  
REGION 3 US ATOMIC ENERGY COMMISSION  
799 ROOSEVELT RD  
GLEN ELLYN IL 60137

DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2 THIS WILL CONFIRM A  
CONVERSATION WITH F MAURA OF YOUR OFFICE AT 1320 HOURS THIS DATE  
CONCERNING PREMATURE ACTUATION OF MAIN STEAM SAFETY VALVE 2-203-4E  
DURING HYDROSTATIC TESTING OF UNIT 2 PRIMARY SYSTEM THE VALVE OPENED  
AT A PRESSURE OF APPROXIMATELY 1085PSIG WHICH IS BEYOND THE 1210  
PLUS OR MINUS 1 PERCENT ALLOWED BY TECHNICAL SPECIFICATIONS THE  
INCIDENT RESULTED IN ONLY MINOR CONTAMINATION WHOLLY CONTAINED  
WITHIN THE DRYWELL THE PROBLEM OCCURRED WITH UNIT 2 SHUTDOWN AND  
BELOW 212 DEGREES FARENHEIT DURING A HYDROSTATIC TEST CONDUCTED  
SUBSEQUENT TO REPAIRS ON 2A RECIRC PUMP DISCHARGE BYPASS LINE

B B STEPHENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION COMMONWEAL  
TH EDISON CO RR 1 MORRIS IL 60450

1510 EDT

MGMCGBC CGO

OCT 7 1974

8305190215 741010  
PDR ADOCK 05000237  
S PDR

