

MGMWSHT HSB
2-020648Z276 10/03/74
ICS IPMBNGZ CSP
8159422921 MGM TDBN MORRIS IL 143 10-03 0200P EDT
ZIP 20545

western union

Mailgram



50-237

J P OLEARY DIRECTOR DIRECTORATE OF LICENSING US ATOMIC ENERGY COMMISSION
WASHINGTON DC 20545

DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2 THIS WILL CONFIRM OUR
CONVERSATION WITH C BROWN OF YOUR OFFICE AT 1020 HOURS THIS DATE
CONCERNING GREATER THAN 0.7 CURIES IN (A) FLOOR DRAIN SAMPLE TANK
THIS TANK WAS PROCESSED BY DISCHARGING TO THE RIVER BEFORE THE
ORIGINAL CURIE CONTENTS OF 0.94 WAS DETERMINED THIS TANK WAS INITIALLY
FILLED AT 0200 HOURS ON 9-25-74 AND AT APPROXIMATELY 0600 HOURS
ON 9-26-74 THE TOTAL ACTIVITY WAS BELOW THE 0.7 CURIE LIMIT THIS
ABNORMAL OCCURRENCE WAS DISCOVERED ON 10-2-74 WHEN THE TECHNICAL
STAFF MADE A REVIEW OF DEVIATION REPORT WHICH HAD BEEN INITIATED
AT THE TIME OF THE REPORT

B B STEPHENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION COMMONWEALTH
EDISON CORR 1 MORRIS IL 60450

1400 EDT

MGMWSHT HSB



8305190436 741015
PDR ADOCK 05000237
S PDR

50-237
incident
COPY SENT REGION

III 10353