

MGMCGBA CGO  
2-013000E110 04/20/74  
ICS IPMBNGZ CSP  
3096542241 MGM TDBN CORDOVA IL 100 04-20 0122P EDT  
ZIP 60137



Mailgram



J KEPPLER, REGIONAL DIRECTOR DIRECTORATE OF REGULATORY OPERATIONS  
REGION 3  
US ATOMIC ENERGY COMMISSION 799 ROOSEVELT RD  
GLEN ELLYN IL 60137


REFERENCE QUAD CITIES NUCLEAR POWER STATION UNIT 1 DOCKET #50-254  
DPR29 APPENDIX A SECTIONS 1.0.A.2, 3.2.A, CABLE 3.2.1, 6.6.B.1.A  
ON APRIL 19 1974 WITH UNIT 1 IN COLD SHUT DOWN FOR THE CURRENT  
REFUELING OUTAGE SERVALENCE TESTS REVEALED 9 OF 16 HPCI HIGH  
TEMPERATURE ISOLATION TEMPERATURE SWITCHES WITH SET POINTS EXCEEDING  
THE LIMITING CONDITION FOR OPERATION OF LESS THAN OR EQUAL TO  
200 DEGREES FAHRENHEIT ALL 16 TEMPERATURE SWITCHES WERE RECALIBRATED  
TO 185 DEGREES FAHRENHEIT  
N J KALIVIANAKIS

1324 EDT

MGMCGBA CGO

8305200278 740429  
PDR ADDCK 05000254  
S PDR

APR 2 1974



UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIRECTORATE OF REGULATORY OPERATIONS  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

TELEPHONE  
(312) 858-2660

*File*

A. RO Inspection Report No. \_\_\_\_\_

Transmittal Date : \_\_\_\_\_

Distribution:  
RO Chief, FS&EB  
RO:HQ (5)  
DR Central Files  
Regulatory Standards (3)  
Licensing (13)  
RO Files

Distribution:  
RO Chief, FS&EB  
RO:HQ (4)  
L:D/D for Fuels & Materials  
DR Central Files  
RO Files

B. RO Inquiry Report No. \_\_\_\_\_

Transmittal Date : \_\_\_\_\_

Distribution:  
RO Chief, FS&EB  
RO:HQ (5)  
DR Central Files  
Regulatory Standards (3)  
Licensing (13)  
RO Files

Distribution:  
RO Chief, FS&EB  
RO:HQ  
DR Central Files  
RO Files

C. Incident Notification From: Commonwealth Edison Co. Docket 50-254  
(Licensee & Docket No. (or License No.))

Transmittal Date : May 23, 1974

Distribution:  
RO Chief, FS&EB  
RO:HQ (4)  
Licensing (4)  
DR Central Files  
RO Files

Distribution:  
RO Chief, FS&EB  
RO:HQ (4)  
L:D/D for Fuels & Materials  
DR Central Files  
RO Files