



Commonwealth Edison

One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

May 11, 1984

Mr. James G. Keppler
Regional Administrator
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: LaSalle County Station Units 1 and 2
Supplemental Response to IE Bulletin 83-07
"Apparently Fraudulent Products Sold By Ray
Miller, Inc."
NRC Docket Nos. 50-373/374

- References (a): IE Bulletin No. 83-07 - R. C. DeYoung letter to
All OLs and CPs dated July 22, 1983 (NL-83-0035)
- (b): IE Bulletin No. 83-07 Supplement 1 - R. C.
DeYoung letter to All OLs and CPs dated
October 26, 1983 (NL-83-0462)
- (c): IE Bulletin No. 83-07 Supplement 2 - R. C.
DeYoung letter to All OLs and CPs dated
December 9, 1983 (NL-83-0695)
- (d): P. L. Barnes letter to J. G. Keppler dated
March 20, 1984 (NL-84-0318)

Dear Mr. Keppler:

Reference (a) requested that the Commonwealth Edison Company provide a written report regarding our review of records for receipt of apparently fraudulent materials sold by Ray Miller, Inc. Reference (d) provided that report.

In Reference (d) we identified three companies who supplied materials during initial construction and who were identified as secondary recipients of Ray Miller material. We were also to provide a report on the results of the review of these companies.

Our Architect Engineer has done a review of QC documentation files on these companies and found no objective evidence that Ray Miller material was received by the secondary respondents and shipped to the primary contractors. Based on this, we feel that we have reasonable assurance that Ray Miller material submitted to secondary respondents was not used on LaSalle County Units 1 and 2.

IE 11
1/6

A review by each of these companies to verify this has not been completed. The results of this review will be reported by September 1, 1984.

To the best of my knowledge and belief the statements contained herein are true and correct. In some respects these statements are not based on my personal knowledge but upon information furnished by other Commonwealth Edison employees, consultants, and contractors. Such information has been reviewed in accordance with Company practice and I believe it to be reliable.

Please address any questions that you or your staff may have concerning our response to IE Bulletin No. 83-07 to this office.

One (1) signed original is being sent directly to the USNRC Document Control Desk in Washington, DC for reproduction and distribution as requested in the Bulletin.

Respectfully,

P. L. Barnes

P. L. Barnes
Nuclear Licensing Administrator

cc: U.S. NRC, Document Control Desk
Washington, DC 20555

RIII Inspectors - LSC

SUBSCRIBED and SWORN to
before me this 11th day
of May, 1984

Rosalie A. Puente
Notary Public

8592N