


U. S. A. E. C.
COMPLIANCE II
ATLANTA, GA.

Aug 14 10 16 AM '72



August 11, 1972

Mr. John G. Davis, Director
Region II Field Office
Directorate of Regulatory Operations
U. S. Atomic Energy Commission
230 Peachtree Street, N. W.
Atlanta, Georgia 30303

Dear Mr. Davis:


Re: RO:II:JGD - Dockets Nos. 50-250 and 50-251

Regarding the verification of valve wall thickness of valves within the reactor coolant pressure boundary of Turkey Point Plant Units 3 and 4, we are actively developing a program to assemble records as requested in your recent letter.

As your inspectors are aware, approximately 10% of the subject valves have been examined ultrasonically to date and in some cases valve wall thickness was increased by approved procedures. Documentation has been examined at the plant site by your inspectors.

At present, a plan is being drawn up to document thickness of the balance of the valves and it will be sent to you by about mid-September. In the meantime, our records on this subject are open to your inspectors as usual to establish that we are complying with your request.

Very truly yours,



James Coughlin
Vice President

JC:rp

8306020211 730410
PDR ADOCK 05000250
Q PDR

Ltr to Florida Power and Light Company fm J. G. Davis
dtd 10/27/72
Ltr to J. G. Davis fm J. Coughlin, FP&L, dtd 8/11/72

DISTRIBUTION:

RO, AD For Procedures
RO, AD For Inspection and Enforcement
L, DD For Reactor Projects
RO, Chief, Reactor Testing and Operations Branch
RO, Chief, Reactor Construction Branch
RO Files 
DR Central Files
PDR
Local PDR
NSIC
OIS

RECEIVED
1972 NOV 8 PM 4 14
U.S. ATOMIC ENERGY COM.
DIVISION OF COMPLIANCE