

James G. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Telecopied Date 8-25-75
or
Telegrammed: GE 12:35 P
DC _____
BY KC

cc:
Bernard C. Rusche, Director
Directorate of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

50-249

SUBJECT: DPE-15, Dresden Nuclear Power Station, Unit 3.

This will confirm a conversation with MR. R. Knop of
your office at 1000 hrs ^{8/24/75} ~~this date~~ concerning INSTRUMENT DRIFT
OF REACTOR HIGH PRESSURE SLAM SWITCHES PS 3-263-
SS A, B AND C DURING INSTRUMENT SURVEILLANCE. THE
SWITCHES WERE BEING CHECKED AT THE CONCLUSION
OF THE PRESENT REFUELING OUTAGE AND HAD NOT
BEEN TESTED SINCE 4/7/75. INACTIVITY IS BELIEVED
RESPONSIBLE FOR DRIFT. SWITCHES ARE MELETRON TYPE,
0-1200 PSIG. MAXIMUM DRIFT WAS 15 PSI.

8306090079 750902
PDR ADOCK 05000249
S PDR

To Call:

GE - 5-858-2660x16 (auto)
DC - 9-1-301-492-7617 (auto) - on 6
WU - 815-942-4449/4321

Station Dist: Originator (copy)

Received 12:43
8/25/75
B. B. Stephenson, Superintendent
Dresden Nuclear Power Station
Commonwealth Edison Company
R.R. #1
Morris, IL 60450