

EV

PLEASE PRINT ALL REQUIRED INFORMATION)

EVENT
TYPE

EVENT DESCRIPTION

VIOLATION

CAUSE DESCRIPTION

DISCOVERY DESCRIPTION

LOCATION OF RELEASE

PERSONNEL EXPOSURES

PERSONNEL INJURIES

OFFSITE CONSEQUENCES

LOSS OR DAMAGE TO FACILITY

PUBLICITY

ADDITIONAL FACTORS CAUSE DESCRIPTION (CONT.)

NAME: TERRANCE E. LANG

PHONE: EXT. 433



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

BBS Ltr. #76-799

November 10, 1976

Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



IE FILE COPY

Enclosed please find Reportable Occurrence report number 50-249/1976-26.
This report is being submitted to your office in accordance with the Dresden
Nuclear Power Station Technical Specifications, Section 6.6.B.

Arthur M. Roberts

for B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:jo

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

11855