



Telegram

1973 JUL -2 PM 3:33

VEE221(1530)(2-045970E183)PD 07/02/73 1530

ICS IPMBNGZ CSP

3096542241 TDBN CORDOVA IL 153 07-02 0330P EST

PMS B GRIER, FONE

US ATOMIC ENERGY COMMISSION REGION 3 COMPLIANCE 799 ROOSEVELT
RD

GLEN ELLYN IL 60137

SUBJECT QUAD CITIES NUCLEAR POWER STATION UNIT ONE AND TWO DOCKET
#50-254 AND 50-265 DPR 29 AND 30 APPENDIX A SECTION 1.0.A.4
AND 6.6.B.1 ON JULY 1 1973 THE SHARED DIESEL GENERATOR WAS FOUND
TO BE INOPERABLE WHEN THE UNIT ONE OPERATOR WAS RELIEVING THE
SHIFT AT ABOUT 1530 HE OBSERVED THAT THE GREEN LIGHT INDICATING
THAT THE 1/2 DIESEL IS SHUT DOWN NOT LIT. A BLOWN FUSE WAS REPLACED
IN THE DIESEL CONTROL CIRCUIT AND THE DIESEL WAS SUCCESSFULLY
TESTED AT 1700 THE LOSS OF CONTROL POWER DURING THE PERIOD THAT

SF-1201 (RS-69) THE FUSE WAS BLOWN RENDERED THE DIESEL INOPERABLE PRIOR TO DISCOVERY

OF THE FAILURE THE MOST RECENT TESTS OF THE DIESEL WAS ON JUNE
29 THE UNIT ONE AND TWO DIESEL WERE OPERABLE AT ALL TIMES THE
CAUSE OF THE BLOWN FUSE IS BEING INVESTIGATED AND BELIEVED TO
BE DUE TO A DEFECTIVE INDICATING BULB OR SOCKET

NICK KALIVIANAKIS

VE-P
AGENCY: [illegible]
Nbr.: [illegible]
Date: 7-3
To be: [illegible]
Attn: [illegible]
933A 85- [illegible]
Mail [illegible]

8306150067 730709
PDR ADOCK 05000254
S PDR