

WU INFOMASTER 1-0401010006 01/06/75
TLX WU IFC USA
096
TWX 7101230475 USAEC-KCS-GTWN

TWX INCOMING

BEH
005

SLO36 WAF139-UCRLKWAPEPIRUE006)PD 01/06/75 1713
ICS IPKENCZ CSP
3159424449 TDM MORRIS IL 60 01-06 0513P EST
~~PIS J. E. STEPHENSON~~ DIRECTOR
DIRECTORATE OF LICENSING WUX U S ATOMIC ENERGY COMMISSION
WASHINGTON DC 20545
SUBJECT: DPR-25, DRESDEN NUCLEAR POWER STATION UNIT 3.

50-249

THIS WILL CONFIRM A CONVERSATION WITH PAUL JOHNSON OF YOUR OFFICE
AT 1445 HOURS THIS DATE CONCERNING FAILURE OF TWO BENGAN-PATERSON
PIPE RESTRAINTS IN UNIT THREE DAYWELL. BOTH SNUDDERS WERE REPLACED
FOLLOWING THEIR DISCOVERY ON 4 JANUARY 75. SEALED MATERIAL IN
BOTH CASES WAS STYRENE-PROPYLENE.

D E STEPHENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION
COMMONWEALTH EDISON CO RR 1 MORRIS ILLINOIS 60450

1950 EST

USAEC-KCS-GTWN

180

8306150608 750106
PDR ADJCK 05000249
S PDR