

101
Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Telecopies Date 3-3-76
or
Telegraphed GE 3:35
DC _____
By KC

cc:
Director
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

SUBJECT: DPR-25, Dresden Nuclear Power Station, Unit 3.

This will confirm a conversation with Mr. R. Knop of your office at 11:30 hrs this date concerning unavailability of the Emergency Electrical Feed to the $\frac{2}{3}$ 'B' Standby Gas Treatment System while the 'A' system was out of service for filter replacement. The Unit 3 Diesel Generator was manually taken out of service inadvertently at 0600 hours, on 3/3/76 due to a loose connection in the manual control circuit. The diesel generator was returned to service at 0925 on 3/3/76, thus making the $\frac{2}{3}$ 'B' Standby Gas Treatment system operable. Had it been necessary to supply feed to the $\frac{2}{3}$ 'B' Standby Gas Treatment system, the cross tie to the Unit 2 emergency electrical system could have been utilized.

8306160109 770411
PDR ADOCK 05000249
S PDR

To Call:
GE - 7-858-2660x16
DC - 9-1-301-492-7617 (auto)
WU - 815-942-4449/4321

Station Dist: Originator (copy)
Incident File (copy)
Telegram File (orig)

B. B. Stephenson, Superintendent
Dresden Nuclear Power Station
Commonwealth Edison Company
R.R. #1
Morris, IL 60450

Telephone: 815-942-2920/2921x212
(telecopy x262)

Rev. 12-75

Received 3/47 3/3

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

Incident Notification From: Commonwealth Edison Company 50-249
(Licensee & Docket No. (or License No.))

Transmittal Date: April 14, 1976 Dresden Station Unit#3

Distribution:

IE Chief, FOSB
IE Chief, FC&EB
IE:HQ(4)
Licensing(4)
DR Central Files
IE Files

Distribution:

IE Chief, FOSB
IE Chief, FC&EB
IE:HQ(4)
L:D/D for Fuels & Materials
DR Central Files
IE Files