



Commonwealth Edison  
Quad-Cities Nuclear Power Station  
Post Office Box 216  
Cordova, Illinois 61242  
Telephone 309/654-2241

NJK-75-514

TELECOPY: Region III, Attention: Mr. C. Feierabend

October 17, 1975

J. Keppler, Regional Director  
Office of Inspection and Enforcement  
Region III  
U. S. NUCLEAR REGULATORY COMMISSION  
799 Roosevelt Road  
Glen Ellyn, IL 60137

REFERENCE: Quad-Cities Nuclear Power Station, Unit 2  
Docket No. 50-265, DPR-30  
Appendix A, Sections 1.0.A.2, 3.1.A, Table 3.1.1.c., 6.6.B.1.a.

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.

On October 16, 1975, during routine monthly surveillance of the High Drywell Pressure Sensors, three of the four Drywell Pressure Switches were found to exceed the Technical Specification setpoint limit of less than 2.0 P.S.I. The instruments were immediately recalibrated and tested satisfactorily.

This occurrence was discussed by telephone with Mr. Knop of your office on October 16, 1975. Further information will be provided by Abnormal Occurrence Report AO 50-265/75-40 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY  
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis  
Station Superintendent

NJK:HGL/dkp

cc: Office of Nuclear Reactor Regulation  
G. A. Abrell