



Commonwealth Edison
Quad-Cities Generating Station
Post Office Box 216
Cordova, Illinois 61242
Telephone 309/654-2241

NJK-75-366

Telecopy: Region III, Attention: Mr. C. Feierabend

July 21, 1975

J. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station, Unit 2
Docket No. 50-265, DPR-30
Appendix A, Sections 1.0.A.5, 6.6.B.1.a

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.

At 7:00PM on July 20, 1975, a leak was discovered in the Unit 2 Main Steam Isolation Valve room. The leak was determined to be the result of a crack on the B feedwater flush line at the point where it is welded to the main feed header.

At 8:30PM an orderly reactor shutdown was commenced. The unit was taken off the line at 12:50AM on July 21st and all rods were in at 4:40AM. Preparations are currently being made for repair of the cracked line.

This occurrence was discussed by telephone with Mr. Feierabend of your office on July 21, 1975. Further information will be provided by Abnormal Occurrence Report AO 50-265/75-24 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N.J. Kalivianakis
Station Superintendent

NJK/SRH/vmb

cc: Director of Office of Nuclear Reactor Regulations
J.S. Abel

8306170161 750729
PDR ADOCK 05000265
S PDR