



Commonwealth Edison
Quad-Cities Nuclear Power Station
Post Office Box 216
Cordova, Illinois 61242
Telephone 309/654-2241

NJK-75-337

Telecopy: Region III, Attention: Mr. C. Feierabend

June 30, 1975



J. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station, Unit 2
Docket No. 50-265, DPR-30
Appendix A, Sections 1.0.A.2, 3.7.A.3, 6.6.B.1.a

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.


At 1:30 a.m. on June 28, 1975, during monthly surveillance testing of the pressure suppression chamber to reactor building vacuum breakers, valves 2-1601-20A and 2-1601-20B failed to open from the control room. The problem was improper operation of the solenoid valves which allow air to open the valves.

The maintenance foreman was contacted by the shift engineer, and the valves were repaired and retested satisfactorily by approximately 4:00 a.m. that same morning.

This occurrence was discussed by telephone with Mr. Hunnicutt of your office on June 28, 1975. Further information will be provided by Abnormal Occurrence Report A0 50-265/75-21 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION


N. J. Kalivianakis
Station Superintendent

NJK/SRH/lk

cc: Director of Office of Nuclear Reactor Regulation
J. S. Abel

8306170195 750708
PDR ADOCK 05000265
S PDR