



Telegram

VEA509(2320)(1-03272303 17)PD 11/06/72 1923

ICS IPMVEIC MVN

ZCZO 00289 TDVE MORRIS ILL 114 11-06 346P CST

PMS MR BOYCE ORIER DIRECTOR DIVN OF COMPLIANCE

US ATOMIC ENERGY COMMISSION REGION 3

799 ROOSEVELT ROAD

GLEN ELLYN ILL 60137

SUBJECT: DPR-25 DRESDEN NUCLEAR POWER STATION UNIT 3.

THIS WILL CONFIRM A CONVERSATION WITH MR H BLANCE OF

YOUR OFFICE AT 1430 HOURS THIS DATE CONCERNING HPCI SYSTEM

INOPERABILITY. AT 0240 NOVEMBER 6 1972, WHILE CONDUCTIN

POST MAINTENANCE SURVEILLANCE DURING UNIT START-UP, THE

HPCI STEAM VALVE 2-2301-4 IN THE DRY WELL WOULD NOT

OPEN. ALTHOUGH THE STARTUP AND HEAT-UP WERE HALTED AT THIS

TIME, THE REACTOR PRESSURE DRIFTED UP TO ABOUT 100

LBS DURING INVESTIAGION OF THE VALVE PROBLEM. AT 0330, THE

SF-1201 (RS-69)

NOV 9 1972

SHIFT BEGAN A SHUT-DOWN OF THE UNIT. AT 0405, WITH REACTOR
PRESSURE 77PSIG AND SUB-CRITICAL, VALVE TESTED SATISFACTORILY.

AT 0415 RESUMED START-UP. SATISFACTORILY TESTED HPCI

AT 0730 AT MINIMUM STEAM PRESSURE OF 110 PSI

W P WORDEN SUPERINTENDENT DRESDEN NUCLEAR POWER STATION
COMMONWEALTH EDISON RURAL ROUTE 1 MORRIS ILLINOIS

8306230240 721129
PDR ADOCK 05000249
S PDR

SF-1201 (RS-69)

NOV 6 PM 10 41

TELEGRAMS (OTHER THAN MONEY ORDERS)
DELIVERY requested? (YES-AGENT, NO-ADDRESSEE)
AGENT SECTION
Nbr. & Name
Date dtd 11/5 Time dtd 1004 To 312-858-2660 By 39
To be made by delivery (Indicate DA or BY)

50249
inquiry