




Commonwealth Edison
Quad-Cities Generating Station
Post Office Box 216
Cordova, Illinois 61242
Telephone 309/654-2241

NJK-75-32

TELECOPY: Region III, Attention: Mr. C. Feierabend

January 15, 1975



J. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
U. S. ATOMIC ENERGY COMMISSION
799 Roosevelt Road
Glen Ellyn, IL 60137

REFERENCE: Quad-Cities Nuclear Power Station, Unit Two
Docket No. 50-265, DPR-30
Appendix A, Sections 1.0.A.2, 3.2.A, 6.6.B.1.a.

Dear Mr. Keppler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.

With Unit Two in the cold shutdown condition for the current refueling outage, quarterly surveillance testing of the main steam line low pressure isolation switches was conducted. Pressure switch 2-261-30B was found to trip at 846 psig thereby violating Technical Specification 3.2.A. The switch was recalibrated to a setpoint of 864 psig. The three other MSL low pressure switches were found to have setpoints of greater than 850 psig, and therefore would have performed the isolation, if low pressure had occurred.

This occurrence was discussed by telephone with Mr. Feierabend of your office on January 14, 1975. Further information will be provided by Abnormal Occurrence Report A0 50-265/75-5 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

[Signature]
N. J. Kalivianakis
Station Superintendent

NJK:SH/dkp

cc: Directorate of Licensing
J. S. Abel

*50-265
inquiry*

525

8306290109 750124
PDR ADOCK 05000265
S PDR

COPY SENT REGION III