



Quad-Cities Generating Station
Post Office Box 216
Davenport, Illinois 52822
Telephone 309/684-2241

NJK-7/4-444

Teletype: Region III, Attention: Mr. G. Falaraband

December 30, 1974

J. Kappler, Regional Director
Directorate of Regulatory Operations
Region III
U. S. Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60132

Reference: Quad-Cities Nuclear Power Station, Unit 2
Deckers NB: 50-265, DPR-30, Appendix A
Sections 1.0.1.2, 3.2.1, Table 3.2.1, 6.6.8.1.a.

Dear Mr. Kappler:

The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.8.1.a within 24 hours of the occurrence.

On December 30, 1974, with Unit 2 in the cold shutdown condition for the current refueling outage, surveillance testing of the main steam line high temperature isolation switch found switch TS-2-261-176 trip setpoint at 222°F increasing.

The switch was recalibrated and functionally tested satisfactory.

All 15 other switches were within the Technical Specification LCO of $\leq 200^{\circ}\text{F}$.

This occurrence was discussed by telephone with Mr. Falaraband of your office on December 30, 1974. Further information will be provided by Abnormal Occurrence Report AD-50-265/74-31 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

QUAD CITIES NUCLEAR POWER STATION
N. J. Kappler

N. J. Kappler
Station Superintendent

NJK/LDR/jeh

cc: Director, Region III
J. L. Allen

8306290287 750109
PDR ADOCK 05000265
S PDR

12/30/74