



**LOUISIANA**  
**POWER & LIGHT**


142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

June 23, 1983

W3I83-0220  
Q-3-A35.07.55

Mr. John T. Collins, Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 55  
"Hold Up and Boric Acid Make Up Tanks  
Incorrect Structural Calculations"  
Seventh Interim Report



REFERENCE: LP&L letter W3I83-0181 dated May 20, 1983.

Dear Mr. Collins:

The above referenced letter indicated submittal of a Final Report to the USNRC no later than June 21, 1983.

At the present time, corrective action has been rescheduled for completion by July 15, 1983.

In view of the above, a Final Report will be submitted by August 5, 1983.

Very truly yours,

F. J. Drummond  
Project Support Manager - Nuclear

FJD/RWP/MAL:keh

cc: 1) Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

3) Mr. E. L. Blake

2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

4) Mr. W. M. Stevenson

8307050204 830623  
PDR ADOCK 05000382  
S PDR

J E-27  
110