



Telegram

1141A EST APR 18 73 LDX001

PD TDMT HARTSVILLE SOCAR 04-11 NFT

PMS JOHN G DAVIS, DIRECTOR OF REGION TWO

AEC DIVN OF COMPLIANCE DRL

230 PEACHTREE ST NE ATLA

IN ACCORDANCE 6.1.C. OF THE TECHNICAL SPECIFICATIONS THE FOLLOWING ABNORMAL OCCURENCE IS REPORTED. WHILE PERFORMING A SAFETY INJECTION PERIODIC TEST ON APRIL 10 1973, AN INADVERTANT LIQUID RELEASE OCCURED RESULTING IN THE RELEASE OF A SMALL AMOUNT OF PARTICULATE AND TRITIUM ACTIVITY TO THE PLANT STORM DRAIN SYSTEM. THIS WAS REPORTED TO MR HERB WHITENER IN PERSON ON APRIL 11, 1973.

B J FURR, MANAGER, H B ROBINSON PLANT BOX 790  
HARTSVILLE S.C. 29550

F-1201 (R5-69)

8307210076 730515  
PDR ADOCK 05000261  
S PDR