

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER												LICENSE TYPE					EVENT TYPE		
01	M	I	P	A	L	1									0	0	-	0	0	0	0	-	0	0			4	1	1	1	1	0	3
7	8	9				14	15									25	26				30	31	32										
01		CONT						L		L		0 5 0 - 0 2 5 5								0 6 2 7 7 6					0 7 2 2 7 6								
7	8	57	58	59	60	61									68	69				74	75				80								

EVENT DESCRIPTION

02	The containment purge supply valve (CV-1808) failed to open during the monthly test.																												80
03	This valve has been tagged closed to meet the requirements for containment integrity																												80
04	(1.4(d) all automatic containment isolation valves are operable or are locked																												80
05	closed). (ER-76-21)																												80
06																													80

SYSTEM CODE				CAUSE CODE		COMPONENT CODE						PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	S	D	E		V A L V E X						A		C 5 8 7				N		
7	8	9	10	11	12							17	43	44				47	48

CAUSE DESCRIPTION

08	Unknown at the present time. The failure will be investigated during a plant outage																												80
09	of sufficient length such that repairs can be made without affecting plant																												80
10	availability.																												80

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION																				
E			1 0 0			NA			b			NA																				
7	8	9	10	11	12	13				44	45	46													80							
FORM OF ACTIVITY RELEASED			CONTENT OF RELEASE			AMOUNT OF ACTIVITY												LOCATION OF RELEASE														
Z			Z			NA												NA														
7	8	9	10	11	12													44	45													80

PERSONNEL EXPOSURES

NUMBER			TYPE		DESCRIPTION																									
0 0 0			Z		NA																									
7	8	9	11	12	13																									80

PERSONNEL INJURIES

NUMBER			DESCRIPTION																										
0 0 0			NA																										
7	8	9	11	12																									80

PROBABLE CONSEQUENCES

15	None, valve failed in the closed position.																												80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																											
Z		NA																											
7	8	9	10																									80	

PUBLICITY

17	NA																												80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	A revised report will be issued after this valve has been returned to service.																												80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																													80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

8308150144 780810
PDR ADOCK 05000255
S PDR



Consumers
Power
Company

General Offices: 212 West Michigan Avenue, Jackson, Michigan 49201 • Area Code 517 788-0550

July 22, 1976

RECEIVED
AUG 03 1976

Mr James G. Keppler
Office of Inspection and Enforcement
Region III
US Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

DOCKET 50-255, LICENSE DPR-20
PALISADES PLANT - ER-76-21
CONTAINMENT PURGE SUPPLY VALVE

Attached is a reportable occurrence which relates to the Palisades Plant. This occurrence has been classified as a condition leading to operation in a degraded mode permitted by a limiting condition of operation.

David A. Bixel
Assistant Nuclear Licensing Administrator

JUL 26 1976

7763

~~COPY SENT REGION III~~