

MGMATLD ATL
2-257850E257 09/14/73

ICS IPMBNGZ CSP

2057298316 MGM IDBN ATHENS AL 10C 09-14 0427P EST
ZIP 30303



western union

Mailgram



US ATOMIC ENERGY DIVISION
REGION 2 DIRECTORATE OF REGULATORY OPERATIONS<230 PEACHTREE ST
NORTHWEST
ATLANTA GA 30303

ON SEPTEMBER 14 1973 DURING ROUTINE SURVEILLANCE TESTING PRESSURE
SWITCH PDIS-71-1A RCIC STEAM FLOW EXCESSIVE WAS FOUND TO BE
OUTSIDE THE TECHNICAL SPECIFICATIONS SET POINT OF LESS THAN
OR EQUAL TO 450 INCHES OF WATER. THE REACTOR WAS IN THE COLD
SHUT DOWN CONDITION

H J GREEN BROWNSFERRY NUCLEAR PLANT

1629 EST

MGMATLD ATL

8308290312 730924
PDR ADOCK 05000259
S FDR

*Incident
50-259/260/276*