



Telegram

655P EST OCT 31 74 AA100

AAE244(1837)(2-036326E304)PD 10/31/74 1837

ICS IPMBNGZ CSP

2057298316 MGM TDBN ATHEN AL 100 10-31 0637P EST
PMS U S ATOMIC ENERGY COMMISSION REGION 2 DIRECTORATE OF REGULATORY
OPERATION

230 PEACHTREE ST NW

ATLANTIA GA 30303

AT 2134 HOURS OCTOBER 30 1974 WHILE UNIT 2 WAS OPERATING AT
26 O/O REACTOR POWER CONDUCTING A START UP TEST THE LOW FEED
WATER FLOW INTERLOCK CAUSED RECIRCULATION PUMP TO RUNBACK TO
MINIMUM SPEED. REACTOR POWER DROPPED TO 17 O/O BEFORE RSCS OPERABILIT
Y WAS CONFIRMED BY SURVEILLANCE TESTING. REACTOR POWER WAS SUBSEQUENT
LY INCREASED ABOVE THAT REQUIRED FOR RSCS OPERABILITY BY INCREASING
RECIRCULATION FLOW AND OPERATION CONTINUED

SF-1201

8308290425 741107
PDR ADOCK 05000260
S PDR